

HOME PROFILE

LOCATION:

8501 NE Going St Portland, OR 97220

YEAR BUILT: 1945 HEATED FLOOR AREA: 1,720 sq.ft. NUMBER OF BEDROOMS: 4

ASSESSMENT

ASSESSMENT DATE: 06/05/2018

SCORE EXPIRATION DATE:

06/05/2026

ASSESSOR:

Phillip Mamula Western Cascade Solutions LLC

PHONE:

503-347-7887

EMAIL:


phil@ propertyexam.com

LICENSE #:

189761

Flip over to learn how to improve this score and use less energy!







Official Assessment | ID# 207700

The Home Energy Score is a national rating System developed by the U.S. Department of Energy. The Score reflects the estimated energy use of a home based upon the home's structure and heating, cooling, and hot water systems. The average score is a 5. Learn more at HomeEnergyScore.gov.

HOW MUCH ENERGY IS THIS HOME LIKELY	TO USE?
Electric: 13,819 kWh/yr	\$1,885
Natural Gas: 0 therms/yr	\$0
Other:	\$376
Renewable Generation:	(\$0)
TOTAL ENERGY COSTS PER YEAR	\$2 261

How much renewable energy does this home generate?

TOTAL ENERGY COSTS PER YEAR \$2,26

THIS HOME'S CARBON FOOTPRINT:



What should my home's carbon footprint be? Between now and 2030, Portlanders should reduce carbon pollution per household to 3 metric tons per year to reach our climate goals.

- Actual energy use and costs may vary based on occupant behavior and other factors.
- Estimated energy costs were calculated based on current utility prices (\$0.14/kwh for electricity; \$1.17/therm for natural gas; \$4.00/gal for heating oil; \$2.43/gal for propane).
- Carbon footprint is based only on estimated home energy use. Carbon emissions are estimated based on utility and fuel-specific emissions factors provided by the OR Department of Energy.
- Relisting 2-7 years after the assessment date requires a free reprint of the Report from us.greenbuildingregistry.com to update energy and carbon information.
- This report meets Oregon's Home Energy Performance Score Standard and complies with Portland City Code Chapter 17.108.



Score with priority improvements:





Estimated **energy savings** with priority improvements:



Estimated **carbon reduction** with priority improvements:



TACKLE ENERGY WASTE TODAY!

Enjoy the rewards of a comfortable, energy efficient home that saves you money.

- det your home energy assessment. Done!
- □ Choose energy improvements from the list of recommendations below.
- Select a contractor (or two, for comparison) and obtain bids. If a new home, discuss with the builder.
 Checkout www.energytrust.org/findacontractor or call toll free 1-866-368-7878.
- Explore financing options at **energytrust.org.**
- Visit **energytrust.org/solutions/insulation-and-air-sealing/** for changes you can make today.

PRIORITY ENERGY IMPROVEMENTS¹

FEATURE

Envelope/Air sealing Attic insulation Heating equipment 50% Water Heater

TODAY'S CONDITION⁴ Not professionally air sealed

Ceiling insulated to R-11 Oil furnace 80% AFUE Electric EF 0.87

RECOMMENDED IMPROVEMENTS³

Professionally air seal Insulate to R-38 or R-49 if code requires it When replacing, upgrade to ENERGY STAR When replacing, upgrade to ENERGY STAR, (EF>=2.67 or UEF>= 2.67)

ADDITIONAL ENERGY RECOMMENDATIONS²

FEATURE	TODAY'S CONDITION ⁴	RECOMMENDED IMPROVEMENTS
Basement wall insulation	Insulated to R-11	
Air Conditioner	N/A	
Air Conditioner	N/A	
Duct insulation	Un-insulated	
Duct sealing	Un-sealed	
Wall insulation	Insulated to R-7	
Floor insulation	Insulated to R-0	
Foundation wall insulation	N/A	
Heating equipment 50%	Electric heat	
Knee Wall insulation	N/A	
Skylights	N/A	
Solar PV	N/A	
Windows	Double-pane, clear glass	When replacing, upgrade to ENERGY STAR

1. To achieve the "Score with Priority Improvements" all recommended improvements in the Priority Energy Improvements section must be completed. All together, these priority improvements have a simple payback of ten years or less.

- 2. Additional energy efficiency improvements may take longer than ten years to make a return on investment but can have a significant impact on the comfort, efficiency and environmental impact of your home.
- 3. If your home has an oil furnace it is recommended you replace it with a high efficiency electric heat pump.
- 4. Today's Condition represents the majority condition for that feature in the home.